

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4749	DATE	May.20.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the Vehicle Stability Control(VSC) system of the subject vehicles, due to an improper programming of the brake control ECU, there is a possibility that speed sensors for a two-wheel drive vehicle may incorrectly detect engine vibration during vehicle idling as rotational speed for the wheel and the ECU could determine that there is an abnormality in the system. If this were to occur, the warning lights will illuminate and the VSC system will be deactivated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-KSP210	[YARIS]	2019-2020	11,373
5BA-MXPA10			6,829
6AA-MXPH10			9,420
		TOTAL	27,622