

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3034	DATE	27th May 2020
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	A spring fracture with the side stand leg in its rest (up) position, will engage the side stand switch thereby creating an engine stall. Engine stalls increase the risk of a crash.		

EBL-HJ1200	Thruxton	2016 - 2017	78
	Thruxton R	2016 - 2017	279
2BL-DHJ1200	Thruxton	2017 - 2018	7
	Thruxton R	2017 - 2018	194
	Truxton TFC	2019	80
TOTAL			638