

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4751	DATE	May 28, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Impeller (plastic impeller) for low pressure fuel pump may swell and deform in fuel as may have become low in plastic density under improper molding conditions. In this case, the impeller can interfere with the pump cover whereby the fuel pump can be precluded from functioning properly and, in the very worst case, such malfunctioning of the fuel pump could cause the engine to stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RW1	「CR-V」	2018-2019	3,190
DBA-RW2			1,757
6AA-RT5			1,432
6AA-RT6			1,222
6AA-ZE4	「INSIGHT」	2018-2019	2,878
DBA-FC1	「CIVIC」	2018-2019	1,427
DAA-KC2	「LEGEND」	2018-2019	521
		TOTAL	12,427