

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4752	DATE	29 May , 2020
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	If the steering system is used severely like when the machine is fully and repeatedly steered, some hose fittings may crack at their ends due to the generated pressure, since their resistance to hydraulic pressure was not properly evaluated. If the machine is used as it is, the hydraulic oil may leak and the steering operation may be disabled.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-WA137	「WA200-8」	2017-2020	671
TOTAL			671