VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4753	DATE	June 16. 2020
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
	hydrostatic transmi not function during applied to the inside continues to be use	ssion is inappropriat heavy towing work, de of the transmiss	e protection control of the e, the protection control may and an excessive load may be ion. Therefore, if the vehicle mission may be damaged, and nable to travel.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
EDR-105B -	[[007]	2011~2012	41	
	「EG97」	2011~2013	71	
	「EG105」	2011~2013	243	
		2011~2013	415	
-	「YT490」	2015	22	
		2015	159	
		2015~2017	669	
	「YT5101」	2015	42	
		2015~2017	82	
	「YT5113」	2015	28	
		2015	151	
		2015~2020	687	
-	「YT5113C」	2015	10	
		2016~2017	232	
-	「YT488A」	2017~2020	168	
	「YT498A」	2017~2020	115	
	「YT4104A」	2017~2020	283	
	「YT5113A」	2017~2020	485	
-	「YT5113AC」	2017~2019	111	
	「TA-C1130」	2018~2020	18	
	「GCR1130」	2019	10	
		TOTAL	4,042	