

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4757	DATE	June 18 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In some disc wheels of the heavy duty truck, due to an inappropriate adjustment for the metallic mold used in rim molding, concentrated stress have occurred in the welded portion connecting the rim and the disc, possibly resulting in lack of strength in the welded portion. Therefore, if the disc wheels are used for a long period, the welded portions may get cracked. In the worst case, these disc wheels may get fractured.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYL77C 2PG-CYL77C	[GIGA]	2020	20
2PG-CYM77C		2020	1
2PG-CYY77C		2020	1
2KG-CYY77CY 2PG-CYY77CY		2020	7
2PG-CYZ77C		2020	5
2PG-CYZ77CJ		2020	2
2KG-EXD52CD 2PG-EXD52CD		2020	32
2KG-EXD52CE		2020	1
2PG-EXD77CG		2020	1
2DG-EXZ52CK		2020	3
		TOTAL	73