VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /

Import Vehicles

CAMPAIGN NO.	4759	DATE	June 18 ,2020
MANUFACTURER		ISUZU BODY CORPORATION	
DESCRIPTION OF DEFECT		In some disc wheels of the heavy duty truck, due to an inappropriate adjustment for the metallic mold used in rim molding, concentrated stress have occurred in the welded portion connecting the rim and the disc, possibly resulting in lack of strength in the welded portion. Therefore, if the disc wheels are used for a long period, the welded portions may get cracked. In the worst case, these disc wheels may get fractured.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-CYZ77C	ISUZU "G1GA"	March 10 ,2020	1
2PG-CYZ77CM		Marchi 16 ,2020~April 27 ,2020	4
2PG-EXD52CD		March 23 ,2020	1
2KG-EXD52CE		April 2 ,2020	2
		TOTAL	8