

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 7 6 7	DATE	June. 25. 2020
MANUFACTURER	TRANTECHS. CO. , LTD		
DESCRIPTION OF DEFECT	In the wheel stopper storage part of the van vehicle class, there was inadequate welding control during manufacturing, some cases where the strength of the welded part of the storage stay is insufficient. For that reason, the welded part of the storage stay may rupture due to running vibration, in the worst case, part of the storage stay and the wheel stopper may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FN1AJG	HINO PROFIA	2018~2020	25
QPG-FN1AYEG			10
2RG-FR1AHG			14
2KG-FC2ABG	HINO RANGER	2019	5
TPG-XZU712M	HINO DUTRO	2019	6
2RG-XZU712M			
		TOTAL	60