

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 7 7 0	DATE	July. 2. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the steel belt of CVT (continuously variable transmission) , due to inadequate control program, the steel belt may get scratched. Therefore, if the driver continues to drive in this condition, in worst case, steel belt may be broken and it may be unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HC26	N I S S A N S E R E N A	2 0 1 2	29,761
DAA-HFC26		~ 2 0 1 3	80,558
DAA-SHC26	S U Z U K I L A N D Y		1,227
		TOTAL	111,546