

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

| CAMPAIGN No. | 4772 | DATE | July 3, 2020 | |
|-----------------------|--|---------------------|-------------------|----|
| MANUFACTURER | UD Trucks Corporation | | | |
| DESCRIPTION OF DEFECT | With regards to the steel disc wheel for heavy-duty trucks, due to the inappropriate metal pattern for rim molding process, surfaces of the rim and the disc may be welded unevenly which might cause insufficient fatigue strength at welded parts. Thus, if the vehicle operates long hours the welded part may crack, in the worst case, the disc wheel may be at a risk of breakage. | | | |
| | | | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | |
| 2PG-CD5CA | Quon | 2020 | 16 | |
| 2PG-CD5CE | | | 1 | |
| 2PG-CD5CL | | | 2 | |
| 2PG-CW5CL | | | 3 | |
| 2PG-CX5BA | | | 2 | |
| 2PG-GK5AAB | | | 3 | |
| | | | TOTAL | 27 |