

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 7 7 6	DATE	July. 9. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the front side member, the welding gun may not touch the vehicle body panel due to incorrect setting of welding equipment, and welding may not be performed at a part of the welding spot. Therefore, the strength of the side member becomes low, and the strength of the vehicle body for securing a passenger space in the case of a front vehicle collision is insufficient, and in worst case, the passenger may be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HE12	N I S S A N   N O T E	2 0 2 0	3
DBA-E12			1
		TOTAL	4