

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4 7 7 1	DATE	July 14, 2020
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	The strength of the chassis frame attachment part of the license plate bracket stays at the rear of the vehicle is insufficient. As a result, cracks may appear in the attachment part due to vibration of the vehicle. If the stay is continued to be used as it is, the cracks may progress and the stay may fall out.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	2KG-FR1EHG	HINO PROFIA	2018-2019	17
HINO	2KG-FR1EHJ	HINO PROFIA	2017-2018	2
HINO	2KG-FS1EHA	HINO PROFIA	2019	1
HINO	2KG-FS1EHG	HINO PROFIA	2018	1
HINO	2KG-FW1EHG	HINO PROFIA	2018-2020	18
HINO	2KG-FW1EHJ	HINO PROFIA	2017	1
HINO	2PG-FN1AJG	HINO PROFIA	2019	1
HINO	2PG-FR1AGA	HINO PROFIA	2018	1
HINO	2PG-FR1AHG	HINO PROFIA	2017-2019	38
HINO	2PG-FR1AHJ	HINO PROFIA	2017-2018	5
HINO	2PG-FR1AJA	HINO PROFIA	2018	1
HINO	2PG-FR1EHG	HINO PROFIA	2017-2019	14
HINO	2PG-FR1EHJ	HINO PROFIA	2017-2019	10
HINO	2PG-FS1AHG	HINO PROFIA	2018-2019	6
HINO	2PG-FW1AHG	HINO PROFIA	2017-2019	108
HINO	2PG-FW1AHJ	HINO PROFIA	2017-2019	23
HINO	2PG-FW1AJG	HINO PROFIA	2019	1
HINO	2PG-FW1EHG	HINO PROFIA	2018-2019	11
HINO	2PG-FW1EHJ	HINO PROFIA	2017-2019	11
HINO	2RG-FR1AHG	HINO PROFIA	2017-2020	78
HINO	2RG-FR1AHJ	HINO PROFIA	2018-2019	2
HINO	2RG-FW1AHG	HINO PROFIA	2017-2020	128
HINO	2RG-FW1AHJ	HINO PROFIA	2017-2019	23
UD TRUCKS	2PG-CD5CA	QUON	2018	3
			Total	504