

| CAMPAIGN No. | 4779 | DATE | 2020.7.14 | | |
|--------------------------|---|------|-----------|--|--|
| MANUFACTURER | HANTA MACHINERY CO. LTD. | | | | |
| DESCRIPTION OF DEFECT | At the rear fender of small type anti-freezing agent spread vehicle, an opening between fender and facing type bracket inappropriate. Therefore there is a potential danger to get a tire in the worst case because a tire may contact to fender and bracket when driving on curving road or getting over a step. | | | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | | NUMBER OF VEHICLE |
|------|--------------------|------------------------|-------|----------------------|
| HINO | DUTRO | 2018~2019 | | 10 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | T | |
| | | | TOTAL | 10 |

(日本工業規格A列4番)