

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4777	DATE			15-Jul-20
MANUFACTURER	KUBOTA Corporation				
DESCRIPTION OF DEFECT	At the agricultural tractor an inappropriately assembly instruction for the powersteering hose can cause the powersteering hose contact with front wheel frame. Therefore if use as it is, the powersteering hose may rub with front wheel frame. It can lead to make a hole and leak the oil.				
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS	
WDR-MGF	M100G-AT	2014~2016	13		
	M110G-AT	2013~2017	189		
YDR-MGF	M110GE-AT	2017~2020	113		
TOTAL			315		