

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	4778	DATE	July.17.2020
MANUFACTURE	Ohara Corporation		
DESCRIPTION OF DEFECT	<p>Traveling vibrations or other factors may cause contact failure in the wiring of the snow vehicle.</p> <p>This is due to improper selection of the terminal box installed between the battery and the fuse box.</p> <p>This can lead to wear on the contact point and eventually, conduction failure. In the worst case, it may cause the snow vehicle to be disabled.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MM04A	Caliber	2018	1
MM04	Caliber	2018	6
		TOTAL	7