

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4790	DATE	July 30, 2020
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Since the precision of the parts of the rod and the cover of the drive piston for switching between forward and backward movement of the vehicle is inadequate, the rod may be broken if the forward and backward movement switching operation is frequently performed. Therefore, the drive piston does not switch from the reverse position, and the vehicle may move backward even if the operating lever is operated to neutral or forward position.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-WA133	「WA40-8」 「WA50-8」	2015-2020	455
YDM-WA133A	「WA40-8」 「WA50-8」	2015-2020	3336
		TOTAL	3791