

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4783	DATE	2020/8/3
MANUFACTURER	KYB Corporation 4-1, Hamamatsu-cho 2-chome, Minato-ku, Tokyo, Japan		
DESCRIPTION OF DEFECT	There is an electric circuit that bypasses the fuse due to improper installation instructions in the "special-purpose construction vehicle that adds an external switch" for the electric water pump of a concrete mixer truck. Therefore, the wiring coating is melted due to an overcurrent at the time of overload, which may lead to a vehicle fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-XZU304E	HINO DUTRO	Feb,05,2009~Feb,15,2009	2
TKG-XZU600E		Nov,11,2014	1
ADG-FC6JCWA	HINO RANGER	Jul,01,2005	1
TKG-FC9JCAA		Jan,07,2017	1
2KG-FC2ABA		Nov,06,2019~Nov,07,2019	2
BDG-FJ7JDWA		Aug,01,2007~Nov,1,2007	2
BDG-FE7JEW A		Jun,07,2007	1
LDG-FJ7JDAA		Dec,02,2010	1
BDG-NKR85N		ISUZU ELF	Dec,18,2007
TKG-NKR85N	Jul,09,2012~Feb,07,2013		5
PB-FSR35D3	ISUZU FORWARD	Mar,29,2005	1
PKG-FSR90S2		Dec,17,2007	1
PJ-FSR34D4S		Apr,19,2007	1
LKG-FTR90S2		Oct,09,2015	1
PA-FE73DB	FUSO CANTER	Nov,23,2004	1
PDG-FE73DB		May,22,2008~May,27,2009	4
QKG-FK72FDZ1	FUSO FIGHTER	Apr,24,2014~May,6,2014	2
KK-LK25A	NISSAN DIESEL CONDOR	Jul,01,2003	1
BDG-MK36C		Dec,25,2007~Dec,16,2010	4
BDG-PK36C		Jun,15,2010	1
TKG-LK38L	UD TRUCKS CONDOR	Sep,15,2016	1
		TOTAL	35