

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

CAMPAIGN No.	4797	DATE	August 20, 2020
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to the V-rod for heavy-duty trucks with leaf spring suspensions, due to inappropriate manufacturing process, the center joint ball sleeve and the flange may fit insufficiently. Thus, when the vehicle repetitively fluctuates, such as driving across level differences, the bolt holding the flange may become loose and the center joint housing may become broken. In the worst case, the vehicle may be at a risk of losing driving stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CD5AL	Quon	2019	1	
2PG-CD5BL 2PG-CD5BLKai		2019	22	
2PG-CD5CL		2019	30	
2PG-CG4CA 2PG-CG4CAKai		2019	4	
2PG-CG5BL		2019	1	
2PG-CG5CL		2019	28	
2PG-CW4AL		2019	16	
2PG-CW5AL		2019	115	
2PG-CW5BL		2019	65	
2PG-CW5CL		2019	33	
2PG-CX5BL		2019	8	
				323