VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

			-	
CAMPAIGN No.	Gai-3073	DATE	2020/8/24	
MANUFACTURE	MASSEY FERGUSON (Japanese Importer :MSK Farm Machinery Corporation CEO Saito Yoshiyuki)			
DESCRIPTION OF DEFECT	In transmissions of agricultural tractors, for the dimensions of the O-ring of the suction filter cover is inappropriate, there is an O-ring is not assembled correctly. Therefore, oil may leak from the gap between the cover and the O-ring. The O-ring of the suction filter needs to be checked and the program in the air supply system needs to be updated. Check the O-ring of the suction filter cover and if the filter is inappropriate, replace with a countermeasure product.			

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-SU66A	MF7718S-4D	2019	1
		TOTAL	1