

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4792	DATE	Aug.27, 2020
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the right headlamp of the LED specification, since the cord wiring of the light source unit, which is an internal component, is improper during the manufacturing process, the cord of the light source unit may interfere with the inside, preventing the lateral movement of the light source unit. Therefore, the optical axis misalignment during use may occur. Such condition may not comply to the Japanese Safety Regulations for Road Vehicles prescribed in Article 32 (headlight standard).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK2	「IMPREZA」	2020	18
DBA-GK3		2020	10
DBA-GK6		2020	7
DBA-GK7		2020	29
DBA-GT2		2020	100
DBA-GT6		2020	22
DBA-GT7		2020	20
DBA-GT3	「IMPREZA」 「XV」	2020	387
5AA-GTE	「XV」	2020	77
		TOTAL	670