

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4800	DATE	Sep. 1. 2020
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	Due to Inadequate durability of horn harness, harness may crack by resonance of engine vibration generated at certain rpm range. This can lead to horn harness breaking resulting in horn failure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
2BL-ZX636G	Ninja ZX-6R	2018	1220	
		2019		
		TOTAL	1220	