

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-3089	DATE	September 2nd, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to the engine control unit (DME) program is inappropriate, it is impossible to properly evaluate the information from the O2 sensor. The engine warning light will not be lit on if there is a failure detected for the O2 sensor by the OBD system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-TS30	BMW X3 M	2019	150
3BA-TS30	BMW X4 M		267
		TOTAL	317