

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3083	DATE	September 3, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The bolted connection between the steering shaft and the steering rack may not have been tightened to the required torque due to improper production process management. As a result, the bolted connection may come loose, and in the worst case, the connection between the steering shaft and the steering rack is uncoupled, and the steering may fail completely.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4MCYRA	Audi Q7 2.0Tq Air suspension / Audi Q7 45Tq Air suspension	2016-2019	7
ABA-4MCYRS	Audi Q7 2.0Tq / Audi Q7 45Tq	2017-2019	2
		Total	9