

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3084	DATE	September 3, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Automatic transmission oil line may be produced by faulty friction-welding due to the use of an incorrect combination of materials in the manufacturing process. As a result, the welded joint is uncoupled and gear oil may leak, and in the worst case, following vehicles maybe involved in accidents by leaked oil onto the road surface.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AAA-F1DCBA	Audi Q8 55Tq Air suspension	2020	55
		Total	55