## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	4802	DATE	Septemb	er.8. 2020
MANUFACTURER	NICHIJO CORPORATION			
DESCRIPTION OF DEFECT	In electrical wiring of rotary snowplow, Due to improper wiring, there is a small gap between the chassis connecting pin and the electric wiring. If the steering operation is repeated, the wiring and the chassis connecting pin come into contact with each other and the wiring coating is damaged. Therefore, in the worst case, Short circuit and engine stop. Alternatively, the wiring may be burned, which may cause a fire.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
Y D S – R 0 6 E	「HTR408」	2 0 1 6 $\sim$ 2 0 2 0 R06E-0002 $\sim$ R06E-0044		3 9
			TOTAL	3 9

[Notes] The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.