## TIRE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic / Import Tires

CAMPAIGN NO.	SOU-13	DATE	September 9,2020		
MANUFACTURER	Sumitomo Rubber Industries, LTD.				
DESCRIPTION OF DEFECT	In some replacement tires for taxis, cracks may appear inside the tread during the manufacturing process due to insufficient tread-rubber strength.  As a result, if the tire continues to be used, the cracks may grow and a portion of the tread may peel off.				

COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
DUNLOP	6.40R14 6P.R. TRIDENT TX-02	Tire for passenger car		48
			Code : 0716 Manufacturing Date 2016 Feb. $14^{th} \sim$ Feb. $20^{th}$	98
			Code : 0317  Manufacturing Date 2017 Jan. 15 <sup>th</sup> ~ Jan. 21 <sup>st</sup>	44
			Code : 2717  Manufacturing Date 2017 Jul. 2 <sup>nd</sup> ∼ Jul. 8 <sup>th</sup>	39
			Code : 4517  Manufacturing Date 2017 Nov. $5^{th} \sim \text{Nov. } 11^{th}$	56
			Code: 5117  Manufacturing Date 2017 Dec. $17^{th} \sim \text{Dec. } 23^{rd}$	79
			Code: 1218  Manufacturing Date 2018 Mar. $25^{th} \sim Mar. 31^{st}$	66
			Code : 2218  Manufacturing Date 2018 Jun. 3 <sup>rd</sup> ∼ Jun. 9 <sup>th</sup>	45
			Code: $3818$ Manufacturing Date 2018 Sep. $23^{rd} \sim \text{Sep. } 29^{th}$	55
			Code: 4418  Manufacturing Date 2018 Nov. $4^{th} \sim \text{Nov. } 10^{th}$	94
			Code: 0619  Manufacturing Date 2019 Feb. 10 <sup>th</sup> ~ Feb. 16 <sup>th</sup>	101
			Code: 3719  Manufacturing Date 2019 Sep. 15 <sup>th</sup> ~ Sep. 21 <sup>st</sup>	42
			TOTAL	767