VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4808	DATE	Sep 24, 2020	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to improper design for drain from the boot for adjuster on both left and right rear view mirror, it may corrode adjuster by accumulated water in the boot. In continuous use of this condition, the rear view mirror adjuster will not hold mirror position correctly causing improper view of the behind traffic condition in the worst case.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BJ-DT11A	Address	2017-2019	10,189
		TOTAL	10,189