

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4811	DATE	Sep. 24. 2020
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	<p>The bracket on the horizontal spare tire carrier of a heavy truck is not strong enough, due to improper design, meaning that some brackets may crack due to the vibration caused when the truck is in operation. For this reason, if you continue to use it as it is, the crack will progress, and in the worst case scenario the spare tire may fall off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FN1AGA 2PG-FN1AGG 2RG-FN1AGG	HINO Profia	2017~2020	956	
2PG-FN1AJG		2017~2020	92	
2PG-FR1AHG 2PG-FR1AHJ 2RG-FR1AHG 2RG-FR1AHJ		2017~2020	119	
2KG-FR1EHG 2KG-FR1EHJ 2PG-FR1EHG 2PG-FR1EHJ		2017~2020	31	
2PG-FR1AJA 2PG-FR1AJG 2PG-FR1AJX		2017~2020	9	
2PG-FR1AGA		2019	3	
2PG-FQ1AJG 2PG-FQ1AJJ		2017~2020	43	
2PG-FS1AHG 2RG-FS1AHG		2018~2020	12	
2DG-FS1EHP 2KG-FS1EHG 2PG-FS1EHG		2018~2019	6	
2PG-FW1AHG 2PG-FW1AHJ 2RG-FW1AHG 2RG-FW1AHJ		2017~2020	353	
2PG-FW1AJG		2018~2019	7	
2DG-FW1EHV		2019~2020	5	
2PG-FH1AGG		2020	2	
		TOTAL	1, 638	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Spare tire carrier bracket	TA391137AA	2017~2020	177
		TOTAL	177