

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3096	DATE	September 24, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Some starter-alternators have a gap on the housing due to manufacturing tolerances. As a result, water may enter into the starter-alternator, and the starter-alternator is shorted out and overheated, and in the worst case, the vehicle fire is broken out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-F2DFBF	Audi A6 40TDIq	2020	153
3CA-F2DFBS	Audi A7SB 40TDIq	2020	87
		Total	240