VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4807	DATE	Oct. 1, 2020	
MANUFACTURER	SUZUKI MOTOR CORPORATION			
DESCRIPTION OF DEFECT	Due to the insufficient adhesion of the paint coating on the front suspension coil spring metal material, the coating may peel off if sand or small stones are being caught between the spring and the spring seat, and the spring material may prematurely corrode. If the vehicle is being used in such condition, the coil spring may be broken in the worst case.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-JB23W	JIMNY	2013~2018	69,818
ABA-JB43W	911/11/11	2013 2018	6,184
ABA-JM23W	AZ-OFFROAD	2013~2014	360
		TOTAL	76,362