

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3101	DATE	2020/10/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain C-, E-Class as well as GLC vehicles (205, 213, 238, and 253 platform) with 4-cylinder gasoline engine the data documenting the correct mounting of the turbocharger oil feed as well as the oil return line might be missing. Due to the missing documentation, no confirmation is available whether the tie rod was correctly mounted to the turbocharger oil feed as well as the oil return line during the assembly process.</p> <p>Should the mountings not meet specification, the mechanical connection of the oil feed as well as the oil return line of the turbocharger might not be ensured permanently. In case of a detached mounting, oil could leak on the oil feed as well as the oil return line of the turbocharger. It cannot be excluded that leaking oil might get in contact with hot components. In this case, the risk of a fire cannot be ruled out.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-205076C	C180	2020	12
5BA-205276C	C180 Wagon		9
5BA-205376	C180 Coupe		1
5BA-205476	C180 Cabriolet		1
5AA-205077	C200	2019	3
5AA-205077C		2020	1
5AA-205078	C200 4MATIC	2019	4
5AA-205078C		2020	2
5AA-205277	C200 Wagon	2019	3
5AA-205278	C200 4MATIC Wagon	2020	2
5AA-205278C			1
5BA-253984	GLC300 4MATIC		
5BA-253384	GLC300 4MATIC Coupe		5

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4AA-213077C	E200	2019	2
		2020	1
4AA-213078C	E200 4MATIC	2019	1
4AA-213278C	E200 4MATIC Wagon	2019	2
		2020	1
4AA-238377C	E200 Coupe	2020	1
5BA-213083C	E300	2019	1
5BA-238383C	E300 Coupe	2020	1
		TOTAL	63