

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3102	DATE	2020/10/1
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain C-Class (205 platform), E-Class (213 platform) and S-Class (222 platform) vehicles the seat belt warning function does not meet the specification after a replacement of the instrument cluster.</p> <p>In case of unbelted occupants on the driver or passenger seat, the seat belt warning function would not display a blinking warning lamp in the instrument cluster and an accompanying warning tone, but instead only a permanently activated warning lamp.</p> <p>Thus, the driver would not receive the full scope of intended warnings in case of an unbelted occupant. Therefore, local legal requirements would not be met.</p> <p>In case of a non-fastened seatbelt, the risk of injury in case of a crash would be increased.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-205340	C180 Coupe	2019	3
DBA-205440	C180 Cabriolet		3
DAA-205077	C200		1
5AA-205077			1
LDA-205014	C220d		1
DAA-205277	C200 Wagon		2
DAA-205277C			1
LDA-205214	C220d Wagon		3
RBA-213242C	E200 Wagon		1
RBA-213245C	E250 Wagon		2017
DBA-222183	S560	2018	1
		TOTAL	18