## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic /Import Vehicles

CAMPAIGN No.	Gai-3097	DATE	2/0ctober/2020		
MANUFACTURER	Automobiles Volvo Car Corporation				
	(Japanese Importer: Volvo Car Japan Limited)				
DESCRIPTION OF	Regarding front windshield wiper arm fixation nut, too low				
DEFECT	torque may lead to loosening nut and wiper arm out of position.				
	Volvo Cars investigations have identified that the front				
	windshield wiper arm fixation nut has been assembled with low				
	torque. It might caus	se reduced or no wipi	ng function.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
VOLVO	[ XC60 ]	2018-2020		8,740
			TOTAL	8,740