VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	4803	DATE	6-October-2020		
MANUFACTURE	Hitachi Construction Machiney Co.,Ltd.				
DESCRIPTION OF DEFECT	Due to the wrong selection of the permanent magnets installed in a fuel pump on wheeled machines, de-magnetization may occur when the temperature is low. In this situation, the high-rotation and high current, which may lead to excess abrasion of brushes of a motor, occurs, and a contact failure and a malfunction of a fuel pump shall occur. In the worst case, the engine can stop during travelling, and restarting the machine may become not possible.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
WDP-H79	「ZW100-5B」	2014-2017	2510	
WDP-H78	「ZW120-5B」	2014-2017	401	
YDP-H88	「ZW100-6」	2017-2020	1436	
YDP-H87	「ZW120-6」	2018-2020	213	
YDR-LADA	「ZX125W-6」	2017-2020	253	
WDP-50D1	「50Z7」	2014-2016	224	
WDP-60D1	「60Z7」	2014-2016	67	
YDP-8SDT21	「8SDT21」	2018-2020	6	
		TOTAL	5110	