

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	外-3105	DATE	October 7. 2020
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	Some bolts that attach the pulleys of water pumps for agricultural tractors have insufficient tightening torque. Therefore, the bolt loosens due to running vibration or the like and the pulley tilts, which may generate an abnormal noise and cause the water pump pulley to fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「JD-6110M」	2020	2	
	「JD-6120M」	2020	9	
	「JD-6130M」	2020	14	
	「JD-6135M」	2020	1	
	「JD-6145M」	2020	1	
	「JD-6130R」	2020	17	
	TOTAL		44	