

# VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4812	DATE	Oct. 8, 2020
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the insufficient strength in the body mount portion of the fuel tank, the fuel tank may suffer a crack in the body mount portion, by the affection of the vehicle vibration while driving.</p> <p>The crack may develop and the fuel may seep from the cracked portion, if the vehicle is continuously used in such condition.</p> <p>The fuel may leak and drip down, in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EBD-DA16T	CARRY	2013~2014	68,961
EBD-DR16T	NT100 CLIPPER		6,484
EBD-DG16T	SCRUM		3,701
EBD-DS16T	MINICAB	2014	3,444
		TOTAL	82,590