

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4813	DATE	October 15, 2020
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the control unit which controls the adaptive LED headlight, due to the inappropriate program for adjusting the optical axis, initialization of optical axis of headlights may not be operated correctly when push button start is pushed and power position turns ON. Therefore, optical axis of headlights may be shifted up and may not be satisfied with the safety standard Article 32 for headlights.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-DM8P	Mazda 「CX-30」	2019-2020	7,513
		Total	7,513