## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4819	DATE	Oct.15,2020
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the rear combination lamp, the density of the resin material is insufficient due to the improper production control of the component parts. If a vehicle with this condition is used over time, due to thermal contraction of such parts, the LED element may be damaged by the interference with the surrounding parts. As a result, the brake lamps and the tail lamps may not turn on in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2017	9,722
DBA-LA160S	MOVE		2,076
DBA-LA150F	CTELL A	2017	979
DBA-LA160F	STELLA		433
		TOTAL	13,210