

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 2 5	DATE	Oct. 22. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the right headlight, due to improper setting of the optical axis adjustment equipment in the vehicle production plant. Therefore, the optical axis may conflict with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-TB17	N I S S A N S Y L P H Y	2 0 1 9	491
		TOTAL	491