

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 2 6	DATE	Oct. 22. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the headlight, due to optical axis adjustment facility was not operating normally, Therefore, the optical axis may conflict with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-GC27	N I S S A N S E R E N A	2 0 2 0	5
DAA-GFC27			2
DAA-HC27			4
DAA-HFC27			5
DBA-T32	N I S S A N X - T R A I L		1
		TOTAL	17