

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 8 2 7	DATE	Oct. 22. 2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the headlight, after adjusting the optical axis, the direction of the headlight may change due to the gap adjustment between the headlight and the vehicle body (fender), Therefore the optical axis may conflict with regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
5BA-Y51	N I S S A N F U G A	2 0 2 0	12
5AA-HY51			15
5BA-KY51			8
5BA-KNY51			8
DAA-HGY51 5AA-HGY51	N I S S A N C I M A	2 0 1 8 ~ 2 0 2 0	8
		TOTAL	(計 51 台)