

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4832	DATE	October 22, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The change pivot bolt, with which the gear change pedal is attached to the vehicle body, may have been installed by an inadequate method whereby the bolt can come loose during the course of forcible upshifting operation and could break eventually, when the gear change pedal could be detached, making it impossible to change gears.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SC82	「CBR1000RR-R」	2020	689
		TOTAL	689