

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	4820	DATE	27-October-2020
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	Selection of the hose of an intercooler on an wheeled excavator was wrong. The hose is to supply air into the engine, however, it can break if it has repetitive compression during the machine traveling. Then, engine loses its output due to lack of pressure charge, and emission gas standards may be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDR-H86	「ZW140-6」	2018-2020	235	
YDR-H85	「ZW150-6」	2018-2020	68	
YDP-8SDT37	「8SDT37」	2019	2	
		TOTAL	305	