

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4830	DATE	October.28.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the fuel pump impeller, due to an improper injection molding process, the resin density of some impellers may be low and they deform by absorption of excessive fuel. If this were to occur, the impeller may interfere with the fuel pump body and fuel pump becomes inoperative, and in the worst case, resulting in engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR80W	[NOAH] [VOXY]	2018	32,598
DBA-ZRR80W "Kai"(modified)			
DBA-ZRR85W			6,364
DAA-ZWR80W			15,190
DBA-ZRR80G	[NOAH] [VOXY] [ESQUIRE]	2018	16,878
DBA-ZRR80G "Kai"(modified)			
DBA-ZRR85G			5,393
DBA-ZRR85G "Kai"(modified)			
DAA-ZWR80G			16,664
DBA-AGH30W	[ALPHARD] [VELLFIRE]	2018	17,684
DBA-AGH35W			2,378
DBA-GGH30W		2018-2019	3,049
DBA-GGH35W			1,253
DAA-AYH30W		2018	7,378

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-ARS210	[CROWN]	2017	488	
3BA-ARS220		2018-2019	929	
6AA-AZSH20		2018	18,736	
6AA-AZSH21			3,202	
6AA-GWS224		2018-2019	2,200	
CBF-TRH200V	[HIACE] [REGIUS ACE]	2018	7,409	
CBF-TRH200K				
CBF-TRH200K “Kai”(modified)				
CBF-TRH211K				182
CBF-TRH216K				300
CBF-TRH221K				343
CBF-TRH226K				378
CBF-TRH223B				264
CBF-TRH223B “Kai”(modified)				
CBF-TRH228B				323
CBF-TRH223B “Kai”(modified)				
CBA-TRH214W				[HIACE]
CBA-TRH214W “Kai”(modified)				
CBA-TRH219W	1,180			
CBA-TRH219W “Kai”(modified)				
CBA-TRH224W	854			
CBA-TRH229W	509			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-AXVH70	[CAMRY]	2018-2019	11,479
CBA-TRJ150W	[LAND CRUISER PRADO]	2018	5,290
DBA-ASU60W	[HARRIER]	2018-2019	1,814
DBA-ASU65W			1,238
CBA-URJ202W	[LAND CRUISER]	2018-2019	2,382
DAA-UEG60	[CENTURY]	2018-2019	666
6AA-UWG60			
DAA-UWG60 “Kai”(modified)			
CBF-TRH221S	[TOYOTA AMBULANCE]	2018	5
CBF-TRH226S			333
DBA-GRS210	[CROWN PATROL CAR]	2018-2019	596
DBA-GRS211			307
DBA-AGL20W	[RX300]	2018-2019	2,700
DBA-AGL25W			964
DAA-GYL20W	[RX450h]	2017-2019	1,329
DAA-GYL25W			1,848
DAA-GYL26W	[RX450hL]	2017-2019	552
DBA-AGZ10	[NX300]	2018-2019	3,865
DBA-AGZ15			1,111
6AA-AZXH10	[ES300h]	2018-2019	2,450
DBA-ASE30	[IS200t] [IS300]	2017-2019	508
DBA-GSE31	[IS350]	2017-2019	27
DAA-AVE30	[IS300h]	2018-2019	1,070

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-AVE35	[IS300h]	2018-2019	150
DBA-VXFA50	[LS500]	2017-2019	678
DBA-VXFA55			191
DAA-GVF50	[LS500h]	2017-2019	505
DAA-GVF55		2018-2019	399
DBA-URZ100	[LC500]	2017-2019	900
DAA-GWZ100	[LC500h]	2017-2019	623
DBA-ARL10	[GS200t] [GS300]	2017-2019	107
DBA-GRL12	[GS350]	2017-2019	153
DBA-GRL16			94
DAA-AWL10	[GS300h]	2018-2019	379
DAA-GWL10	[GS450h]	2018-2019	327
DBA-URJ201W	[LX570]	2018-2019	944
DBA-ASC10	[RC200t] [RC300]	2017-2019	258
DBA-GSC10	[RC350]	2017-2019	126
DAA-AVC10	[RC300h]	2018-2019	296
DAA-AXVH70N	[ALTIS]	2018-2019	60
		TOTAL	210,363