

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4838	DATE	Nov. 6, 2020
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>①Due to the improper clamping position of the brake pipes, the brake pipes may come contact with the vehicle body or with the fuel vapor pipe. Therefore, the brake pipe may be damaged, resulting in the brake fluid leakage and loss of the brake performance, or the fuel vapor pipe may be damaged, resulting in the fuel vapor leakage.</p> <p>②Due to the improper fitting direction of the fuel filler hose, the fuel filler hose may be deformed. If the vehicle is being used in such condition, the fuel filler hose may be cracked and the fuel may leak in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-JB64W	JIMNY	2020	798	①592 ②798
		TOTAL	798	①592 ②798