VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3124	DATE	Nov 6 th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The front axle carrier has insufficient welding strength due to improper welding process during the manufacturing. Therefore, the welding part may break due to the vibration of the road surface, and in the worst case, the customer can get into an uncontrollable driving situation due to loss of wheel control.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-CV30A	BMW X5 xDrive 35d	2020	1
3DA-CV30S	BMW X5 xDrive 35d	2020	1
3BA-CY44	BMW X6 M50i	2020	1
3DA-GT30	BMW X6 xDrive 35d	2020	1
3DA-CW30	BMW X7 xDrive 35d	2020	2
		TOTAL	6