

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4833	DATE	November 10, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the electric forklift, due to the small amount of washers used, the bolts that support transformer for battery charging may be loosened and come off by the vibration from road surface. If it is continuously used in the state, the transformer may drop from the chassis, in the worst case, may contact with the power cables, create short cut circuit between these parts and may cause fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
244AA	「TRANSER」	2018 ~ 2019	5
254AA		2018 ~ 2019	3
		TOTAL	8