

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4840	DATE	November 11, 2020
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	With the internal-combustion engine forklift vehicles, there are cases that the oil filter mounted on the torque converter is improperly selected for the power transmission device. There is a possibility that vibration from the vehicle may damage the screw for mounting the oil filter element and lead to oil leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SC-4FD120	-	2004 - 2008	42
SC-4FDK160		2004 - 2008	35
SC-4FD230		2004 - 2008	19
SD-4FD240		2004 - 2008	17
EDR-4FD120		2008 - 2013	19
EDR-4FDK160		2008 - 2015	35
EDR-4FD230		2009 - 2013	12
JDS-4FD240		2008 - 2013	18
YDR-5FD120	TOYOTA FORKLIFT	2017 - 2020	20
YDR-5FDK160		2017 - 2020	51
YDR-5FD230		2017 - 2020	15
YDS-5FD240		2016 - 2020	18
		TOTAL	301