VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4842	DATE	November 12 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		With regard to the fuel injection systems in medium duty trucks and buses, sealability of some injector gaskets is insufficient due to improper tightening torque of the injector attachment bolts. Consequently, combustion gas may leak, and the attachment bolts of the injector may come loose, causing the vibration to increase. This may result in breakage of the bolts, potentially leading to the engine stop and making the vehicles undrivable.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90S1 SKG-FRR90S2 SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2010-2017	73,517
SDG-FRS90S1 SDG-FRS90S2 SKG-FRS90S2 TKG-FRS90S2		2011-2017	373
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2010-2017	5,090
SDG-FSS90S1 SDG-FSS90S2 SKG-FSS90S2 SPG-FSS90S2		2011-2017	413
LKG-FTR90S2 LKG-FTR90T2 LPG-FTR90S2 LPG-FTR90T2		2010-2017	5,698
SDG-GSR90S2		2011-2014	55
SDG-LR290J1 SKG-LR290J1	[ERGA MIO]	2011-2015	799
		TOTAL	85,945