

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

|                       |  |      |               |
|-----------------------|--|------|---------------|
| CAMPAIGN No.          | 4843   | DATE | Nov. 12. 2020 |
| MANUFACTURER          | Hino Motors, Ltd.  |      |               |
| DESCRIPTION OF DEFECT | With regard to the fuel injection systems in medium duty buses, sealability of some injector gaskets is insufficient due to improper tightening torque of the injector attachment bolts. Consequently, combustion gas may leak, and the attachment bolts of the injector may come loose, causing the vibration to increase. This may result in breakage of the bolts, potentially leading to the engine stop and making the vehicles undrivable. |      |               |

| TYPE                       | COMMERCIAL NAME   | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------------------------|-------------------|---------------------|-------------------|
| SDG-KR290J1<br>SKG-KR290J1 | [HINO Rainbow II] | 2011~2015           | 658               |
|                            |                   | TOTAL               | 658               |